



PHOTO 1 M1019 SOMERSET STREET: GENERAL VIEW (LOOKING NORTH)





PHOTO 2 M1019 SOMERSET STREET: GENERAL VIEW (LOOKING WEST)





PHOTO 3 M1019 SOMERSET STREET: LOOKING EAST AT ADJACENT UPSTREAM STRUCTURE





PHOTO 4 M1019 SOMERSET STREET: LOOKING WEST AT ACCESS MANHOLE AND DRAINAGE INLET





**PHOTO 5 M1019 SOMERSET STREET: LOOKING NORTH AT TELEPHONE CONDUITS**





**PHOTO 6 M1019 SOMERSET STREET: LOOKING WEST AT ADJACENT DOWNSTREAM STRUCTURE.  
IT ALSO EXHIBITED SEVERELY CORRODED STRINGER AND SPALLED ABUTMENT**





03.02.2015 15:44

PHOTO 7 M1019 SOMERSET STREET: LOOKING EAST AT LOW CLEARANCE STRUCTURE AND SEVERELY CORRODED STRINGERS