## **BID TABULATION SHEET**

**Title:** Replacement Battery UPS Modules - For Towers **Opening Date:** Thursday, October 1, 2015 - 2:30pm

Contract #: CC-0002-15

Total Bids Received: 8	Signed Proposal	Stock Disclose	Non- Collusion	Affirm Action	NJ BRC	IRAN	Co-Op	CD	Excep.	Notes	
Gold Type Business Machines											
351 Paterson Ave. East Rutherford, NJ 07073	Х	Х	Х	24180	Х	Х	N/A	Y	N		
Critical Power USA 1539 Tilco Dr. Frederick, MD 21704	Х	Х	Х	Х	Х	Х	N/A	Y	N		
United Power System 801 3rd Street Whitehall, PA 18052	х	Х	х	Х	Х	Х	N/A	Y	Y	Exception: Valid for 60 days / Re-build modules on site	
Unipower LLC. 2760 Emerick Blvd. Bethlehem, PA 18020	Х	Х	Х	42289	Х	Х	N/A	Y	Y	Exception: Deka HR3000 replaces Sigmas Tek SP12-75 / Deka HR3500 replaces Eaton VRLA 12330W4FR	
United Power Battery 6833 Joyce Street Arvada, CO 80007	х	Х	х	Х	Х	Х	N/A	N	Y	Exception: Quantity (Full Replacement)	
NorthEast Battery 240 Washington St. Auburn, MA 01501	х	Х	х	Х	Х	Х	N/A	Y	Y	Exception: Quantity (Full Replacement)	
Weissco Power 516 County Road 513 Califon, NJ 07830	Х	Х	х	Х	Х	Х	N/A	Y	N		
Base Power Services 8 Ellen Drive Rockaway, NJ 07866	х	Х	х	х	х	х	N/A	Υ	N		

Replacement Battery UPS Modules - For Towers Contract #CC-0002-15	Gold Type Business Machines	Critical Power USA	*United Power System	*Unipower LLC.	*United Power Battery	*NorthEast Battery	Weissco Power	Base Power Services
Battery / Module Model	Unit Cost Per Battery / Module Assembly (Includes Installation)							
Sigmas Tek SPX12-100FR	\$115.00	\$104.00	\$2,291.60	\$102.38	\$90.00	\$9,122.13	\$55.00	\$91.67
Sigmas Tek SP12-75	\$170.00	\$129.25	\$12,494.00	\$183.25	\$135.00	\$17,119.69	\$129.00	\$138.75
Eaton VLRA 12330W4FR	\$289.00	\$180.00	\$6,750.00	\$222.65	\$180.00	\$7,651.12	\$165.00	\$169.44
Eaton ASY-0529	\$275.00	\$121.00	\$25,343.00	\$273.73	\$125.00	\$39,406.88	\$107.00	\$71.01
APC SYBT5	\$475.00	\$279.00	\$6,298.00	\$567.61	\$350.00	\$13,003.20	\$220.00	\$162.50
Tripplite RBC2030 pack	\$1,010.00	\$519.00	\$3,430.00	\$1,150.69	\$600.00	\$6,446.64	\$495.00	\$850.00

<sup>\*</sup>Exceptions Noted